


● 分解図

EXPLODED VIEW

＜リヤセクション＞

<Rear Section>



LA232-01



UM766



LM522-02

3x11mm

2 x 11 mm pins
are not used.