

● Symbols used throughout the instruction manual, comprise:



Cut off shaded portion.



5mm
Drill holes with the specified diameter.



Pay close attention here!



Must be purchased separately.




Assemble left and right sides the same way.

PARTS


TAPPING SCREW ----- X10

DOUBLE-SIDED TAPE ----- X1

PS PARTS



ELECTROPLATED PARTS



PLASTIC PARTS

